BUILDING STRUCTURE INVENTORY FORM



NYSOFFICE OF PARKS, RECREATION IF AND A HISTORIC PRESERVATION
DIVISION FOR HISTORIC PRESERVATION

PARTICIPATION OF THE PARTY OF	AND REPORT OF THE PARTY.	of Street Property of		The state of the s
FOR O	CEIGE	CEON	Value of the	
The second second				
		10.0		
中华生活的国际工程				
INHOIT	-			
UNIQU	F 211F		建设设置	等于他们的
		Victoria de la como	ALTO COMPANY	and the Market State of the
QUAD.	AND A SHARE SHARE		Application of the second	41 2 3 3 3
		a House Market Continue	CONTRACTOR NO.	The second second
SERIES			10 TO	115 (4.5)
	A CONTRACTOR	N. Silvedon (Willer)		
NEG. N	A		2.00	
"INCO! TA	U.	reconstruction of the party of the	MAN CHEST SHEET	A TO LOS DE LA COMPANSA DEL COMPANSA DEL COMPANSA DE LA COMPANSA DEL COMPANSA DEL COMPANSA DEL COMPANSA DE LA COMPANSA DEL COMPANSA DE LA COM

(518) 47/4-0479	NEG. NO.
· YOUR NAMI	SELSPETH STANFIELD DATE:
YOUR ADDI	RESS:TELEPHONE:
ORGANIZAT	ION (if any):
IDENTIFICATION	경기 :
I. BUILDING NAM	E(S):
2. COUNTY:	
3. STREET LOCAT	MON: 133 Chameins Start
4. OWNERSHIP:	a. public b. private
5. PRESENT OWN	ER: MARIEM, KOTSONES ADDRESS: 133 CHEMUNG ST.
6. USE: Original: _	Present:
7. ACCESSIBILITY	
	Interior accessible: Explain NO, PRIVATE 855.
DESCRIPTION	. , ,
8. BUILDING	a. clapboard 🗆 b. stone 🗀 c. brick 🗀 d. board and batten 🗀
MATERIAL:	e. cobblestone [f. shingles [g. stucco [other: Alominum 81D
9. STRUCTURAL	a. wood frame with interlocking joints
SYSTEM:	b. wood frame with light members 🔼
(if known)	c. masonry load bearing walls
	d. metal (explain)
• · · · · · · · · · · · · · · · · · · ·	e. other
10. CONDITION:	a. excellent b. good c. fair d. deteriorated deteriorated
II. INTEGRITY:	a. original site b. moved if so, when?
	c. list major alterations and dates (if known):
	SEE CONTINUATION SHEET
	01 - 011 011 01100 I

12. PHOTO:

13. MAP:



CONTINUATION SHEET, Page 1 133 Chemung Street Corning, New York

11. INTEGRITY (major alterations):

The entire building has been covered with horizontal aluminum siding. A wrought iron railing was also added to the porch steps.

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

This structure is situated on the west side of Chemung Street, across from the Corning Hospital. This block of Chemung Street features a variety of small to mid-sized vernacular structures, most built at the turn of the twentieth century. The setbacks of these houses are all very similar.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE:

This house was constructed between 1926 and 1930, a time when the Colonial Revival Style was very popular. According to A Field Guide to American Houses (McAlester), the style was inspired by early English Colonial architecture, but was not always true to the original. This house seems to have been more influenced by the Greek Revival Style, which was not uncommon for this time.

This structure features a front (east) facing gable on the two story northern portion with a one story gable roof wing. The roof line of the rear wing begins at the eave of the front roof. The north facade features two dormers that bisect the eave line. The east facade of the main portion has a hip roof porch. This has square support columns, a closed rail, and wing walls. All the windows are six-over-one double-hung sash. There are two entrances from the porch, one is a wood paneled and the other is multi-light (18).

The structure is clad in horizontal aluminum siding. The foundation is molded concrete block in a rough faced ashlar pattern.

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

The current structure at 133 Chemung Street is located on the northeast portion of Lot #7 and a portion of Lot #8 of Block 43 Corning. There has been structures on this section of Chemung Street since 1888, but there have been changes. This particular portion of Lot #7 has been owned by two families since 1871.



133 Cheming

APPEAR CONTRACTOR CONT