DI	III NINC STDII		NTODY FORM	FOR OFFICE USE ONLY
DI NE	UILDING STRUC VISION OF HISTOR EW YORK STATE F LBANY, NEW YORI	RIC PRESERVA PARKS AND RE	ATION CREATION	UNIQUE SITE NO QUAD SERIES NEG. NO
	YOUR ADD	E: Robert Pick RESS: 106 W. ΓΙΟΝ (if any):		DATE: Fall 1993 TELEPHONE: (607) 255-4331 op at Cornell University
**	******	**********	**********	**********
1. 2. 3. 4. 5.	ENTIFICATION BUILDING NAM COUNTY: Steub STREET LOCAT OWNERSHIP: PRESENT OWN USE: Original:	ME(S): pen ΓΙΟΝ: 106 Eas a. public [] ER: James and		
7.	ACCESSIBILITY	Y TO PUBLIC	Exterior visible from public ro	pad: yes [x] no [] no [x] Explain: private residence
DE	ESCRIPTION			
8.	BUILDING MAT	ΓERIAL:	a. clapboard [x] b. stone [] c. cobblestone [] f. shingles	c. brick [] d. board & batten [] [x] g. stucco [] other:
9.	STRUCTURAL SYSTEM:		 a. wood frame with interlocking joints [] b. wood frame with light members [x] c. masonry load bearing walls [] d. metal [] explain: e. other [] explain: 	
10.	CONDITION:	a. excellent []	b. good [x] c. fair [] d. dete	riorated []
11.	INTEGRITY:	a. original sitec. list major al	[x] b. moved [] if so, when? terations and dates (if known):	See Continuation Sheet
12.	РНОТО:		13. MA	AP:

14.	THREATS TO BUILDING:	a. none known [x]b. zoning []c. roads []d. developers []e. deterioration []f. other:		
15.	RELATED OUTBUILDING	S AND PROPERTY: a. barn [] b. carriage house [] c. garage [x] d. privy [] e. shed [] f. greenhouse [] g. shop [] h. gardens [] i. landscape features: See Continuation Sheet j. other:		
16.		BUILDING: (Check more than one if necessary) a. open land [] b. woodland [] c. scattered buildings [] d. densely built-up [] e. commercial [] f. industrial [] g. residential [x] h. other:		
17.	INTERRELATIONSHIP OF BUILDINGS AND SURROUNDINGS:			
	See Continuation	on Sheet		
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE: (Including interior features if known)			
	See Continuation	on Sheet		
SIGN 19.	IFICANCE: DATE OF INITIAL CONSTR	RUCTION: ca. 1907		
	ARCHITECT:			
	BUILDER:			
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE:			
	See Continuation	on Sheet		
21.	SOURCES:			
	See Continuation	on Sheet		
22.	THEME:			
		·		

CONTINUATION SHEET, Page 1 106 East Fifth Street Corning, New York

11c. INTEGRITY: Major alterations and dates.

This house has been extensively altered. Between 1913 and 1921 a one-story auto garage was added in the southeast corner of the lot. After 1948, the one-story porch on the east was enclosed to create a sunroom. In 1988 an eight-foot extension to the sunroom was added on its east side. In 1990 an 18' x 10' one-story addition was attached to the rear (south) of the house. In 1993 exterior work on the roof was occurring on the south side of the structure.

17 INTERRELATIONSHIP OF BUILDINGS AND SURROUNDINGS:

Located on the south side of East Fifth Street, facing north, this residence is one in a group of late nineteenth- and early twentieth-century homes which are similar in scale. The setback for this residence is similar to that of its neighbor to the west. As this house is on the corner of Fifth and Wall streets, its setback is nearly equal in both directions. However, the setback on the Fifth Street (north) side is terraced and there are two substantial trees near the roadside on the north.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE:

This side-facing gambrel-roofed Colonial Revival-style house has been extensively altered especially on its east and south facades. The gambrel roof, with shed dormers on both the front (north) and rear (south) facades creates a two-and-a-half-story structure. The front (north) facade shows the three-bay composition of the house. An entrance door is located in the center bay. Sheltering the entrance is a porch, with Doric columns supporting a flat roof. The porch railing is enclosed. The shed dormers at the second story level on both the front and rear facades are centered east-to-west and contain three windows each. On the rear (south) facade, there is an additional shed dormer at the third story level. It contains four windows asymmetrically set. All of the second story exterior walls are clad in wood shingles.

The sunroom addition to the east is covered by a hipped roof, as is the addition at the rear. The sunroom has several skylights in the roof. The substantial garage in the southwest corner of the lot has a low-pitched gable roof. The roofs are covered with asphalt shingles. The original foundation is limestone; the additions have concrete foundations.

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

106 East Fifth Street was built ca. 1907 for Nathan R. Wickersham on land he purchased from Mark Tucker and Helen A. Hunt. All of this land was originally owned by Adelaide J. Harvey, who purchased the land in the 1850s. Mr. Wickersham also owned the adjacent property to the east, 112 East Fifth Street.

In 1936 the property passed to Rowland deB. Wickersham, son of the original owner. In 1956 James M. Brown purchased the property from the younger Wickersham. The current owners, James A. and Joanna P. Smith purchased the house in 1964. Mr. Smith is the president of Corning Building Company in Corning, NY.

CONTINUATION SHEET, Page 2 106 East fifth Street Corning, New York

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: (Continued)

Also, an easement was granted to the owners of 112 East Fifth Street in 1911 creating a right-of-way that allowed access to 112 East Fifth Street from Wall Street. The right-of-way crosses just to the south of the garage at the southwest corner of the property associated with 106 East Fifth Street.

21. SOURCES:

Auwaerter, John. Reconnaissance Level Survey - Southside Neighborhood Proposed Historic District - Corning, New York. Ithaca: Cornell University, 1991.

McAlester, Virginia and Lee McAlester. *A Field Guide to American Houses*. New York: Alfred A. Knopf, 1992.

Corning City Directories, Hanford 1893-1959.

Sanborn Map Company. Fire Insurance Maps of Corning, New York, (1903, 1908, 1913, 1921, 1930 and 1930R)

Steuben County Deed Records, Steuben County Clerk's Office, Bath, New York.



ull of 106 East 5th



