



14. THREATS TO BUILDING: a. none known  b. zoning  c. roads   
d. developers  e. deterioration   
f. other:

15. RELATED OUTBUILDINGS AND PROPERTY:  
a. barn  b. carriage house  c. garage   
d. privy  e. shed  f. greenhouse   
g. shop  h. gardens   
i. landscape features:  
j. other:

16. SURROUNDINGS OF THE BUILDING:  
a. open land  b. woodland   
c. scattered buildings   
d. densely built-up  e. commercial   
f. industrial  g. residential   
h. other:

17. INTERRELATIONSHIP OF THE BUILDING AND SURROUNDINGS:

See Continuation Sheet

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE:

See Continuation Sheet

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: ca. 1930

ARCHITECT:

BUILDER:

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

See Continuation Sheet

21. SOURCES:

See Continuation Sheet

22. THEME:

CONTINUATION SHEET, Page 1  
120 East Fifth Street  
Corning, New York

11c. MAJOR ALTERATIONS AND DATES:

There have been no major alterations to the structure and 120 East Fifth Street.

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

The structure at 120 East Fifth Street is situated on a large lot measuring 105 feet by 255 feet. The house is set well back from the street, and is consistent with the other structures on this section of East Fifth Street in terms of setback. There is a large double garage at the south end of the lot. Access to the garage is off of Chemung Street, one half-block to the east.

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE:

This modern brick structure was constructed in approximately 1930, and was built in the Colonial-Adams style. The house consists of one large gable running parallel to the street. The gable ends are facing east and west. The entry is on the north, or front facade, and is covered with a deep, pedimented portico. The pediment over the front door is "broken", and has a heavy cornice and prominent dentils. The cornice runs under the eaves on the north facade and around on to the gable ends where it terminates at the heavy returns. There is a brick chimney at the east gable wall; partially obscured by a brick addition on that side of the structure. The north, or front facade is three bays wide. The portico is centered and flanked on either side by a set of paired windows. The same pattern is repeated on the second floor, except the center set is narrower than the two on each end. Above the eaves, three gabled dormers, also with broken pediments, project out from the roof.

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

This structure is a good (modern) example of a Colonial-Adams style house. Various members of Corning Glassworks middle management have lived in the structure since it was built.

CONTINUATION SHEET, Page 2  
120 East Fifth Street  
Corning, New York

21. SOURCES:

Mc Alester, Virginia & Lee. A Field Guide to American Houses. New York: Alfred A. Knopf, 1991

Corning City Directories, 1928-29, 1930-31. 1935.

Map of Corning. Buffalo; H. Brewer and C. A. Canfield, 1855.



Map of Corning. Corning: Harry C. Heermanns, City Engineer, 1893

Sanborn Map Company. Fire Insurance Maps of Corning, New York, 1903, 1908, 1915, 1920, 1930, 1930-revised in 1948.

Steuben County Deed Records, Steuben County Clerk's Office, Bath, New York.

ADDITIONAL PHOTOGRAPHS:

M. SMITH



120 East 5th Street (both)