

BUILDING-STRUCTURE INVENTORY FORM

FOR OFFICE USE ONLY

DIVISION FOR HISTORIC PRESERVATION  
NEW YORK STATE PARKS AND RECREATION  
ALBANY, NEW YORK (518) 474-0479

UNIQUE SITE NO.  
QUAD  
SERIES  
NEG. NO.

YOUR NAME: John R. Steinmeyer  
YOUR ADDRESS: 106 W. Sibley Hall, Ithaca, NY  
ORGANIZATION (if any): Cornell University

DATE: 15 May 1992  
TELEPHONE: (607)255-0751

\*\*\*\*\*

IDENTIFICATION

- 1. BUILDING NAME(S):
- 2. COUNTY: Steuben TOWN/CITY: Corning VILLAGE:
- 3. STREET LOCATION: 170 Cedar
- 4. OWNERSHIP: a. public[ ] b. private [X]
- 5. PRESENT OWNER: Larry V. and Sun Hwa Sample ADDRESS: 170 Cedar Street  
Present: residence
- 6. USE: Original: residence
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes[X] No[ ]

Interior accessible: no. private residence

DESCRIPTION

- 8. BUILDING MATERIAL: a. clapboard[ ] b. stone[ ] c. brick[X] d. board & batten[ ]  
e. cobblestone[ ] f. shingles[X] g. stucco[ ] other:
- 9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints[ ]  
b. wood frame with light members[X]  
c. masonry load bearing walls[X]  
d. metal (explain)  
e. other
- 10. CONDITION: a. excellent[ ] b. good[X] c. fair[ ] d. deteriorated[ ]
- 11. INTEGRITY: a. original site[X] b. moved[ ] if so, when?  
c. list major alterations and dates (if known):
- 12. PHOTO:
- 13. MAP:



14. THREATS TO BUILDING: a. none known[X] b. zoning[ ] c. roads[ ]  
d. developers[ ] e. deterioration[ ]  
f. other:
15. RELATED OUT BUILDINGS AND PROPERTY:  
a. barn[ ] b. carriage house[ ] c. garage[ ]  
d. privy[ ] e. shed[ ] f. greenhouse[ ]  
g. shop[ ] h. gardens[ ]  
i. landscape features:  
j. other:
16. SURROUNDINGS OF THE BUILDING (CHECK MORE THAN ONE IF NECESSARY)  
a. open land[ ] b. woodland[ ]  
c. scattered buildings[ ]  
d. densely built-up[X] e. commercial[ ]  
f. industrial[ ] g. residential[X]  
h. other:

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

See Continuation Sheet

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE:

See Continuation Sheet

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: ca. 1903

ARCHITECT:

BUILDER:

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

See Continuation Sheet

21. SOURCES:

See Continuation Sheet

22. THEME:





← 170  
Cedar