		FOR OFFICE USE ONLY	
BUILDING-STRUC	CTURE INVENTORY FORM	\mathbf{M}	
		UNIQUE SITE NO	
DIVISION FOR HISTORIC PRESERVATION		QUADSERIESNEG. No	
NEW YORK STATE PARKS AND RECREATION		SERIES	
ALBANY, NEW YOR	RK (518) 474-0479	NEG. No	
MOUD MANGE	Toronto M. Malla	DATE: Fall 1993	
YOUR NAME: Ivette M. Valle YOUR ADDRESS: 106 W. Sibley Hall		DATE: Fall 1995 TELEDITONE: (407) 2554221	
YOUR ADDRESS: 100 W. Stoley Hall		TELEPHONE: (607) 2554331	
	ON (if any): Preservation Planning	g worksnop, Cornell University ************************************	
		<u> </u>	
<u>IDENTIFICATION</u>			
1. BUILDING NAME	$\Sigma(S)$:	VIII LACE.	
2. COUNTY: Steuben TOWN/CITY: Corning VILLAGE: 3. STREET LOCATION: 238 Chestnut Street			
A OWNED SHID	or public [] he private [· Y 1	
4. OWNERSHIP: a: public [] b: private [X] 5. PRESENT OWNER: Marion H. Holmes & Helen Searles ADDRESS: 217 Oneida Pl.			
6. USE: Original: Single-family residence Present: Single-family residence			
7: ACCESSIBILITY	ΓΟ PUBLIC: Exterior visible fr	om public road: Yes [X] No []	
7.11CCEOUIDIEIT 1	Interior accessible: Yes	[] No [X] Explain: Private residence	
		• • • •	
DESCRIPTION			
8. BUILDING MATERIAL: a. clapboard [X] b. stone [] c. brick [] d. board & batten []			
	e. cobblestone [] f. shir	ngles [] g. stucco [] other:	
9. STRUCTURAL SY		th interlocking joints []	
	b. wood frame wi	th light members [X]	
		earing walls []	
	d. metal (explain)		
	e. other		
10. CONDITION:	n avcellent [] h good	[X] c. fair [] d. deteriorated []	
10. CONDITION:	a. excellent [] b. good	[A] c. lan [] d. deteriorated []	
11. INTEGRITY: a. original site [X] b. moved [] if so, when?		l if so, when?	
	c. list major alterations and dates	(If known): See Continuation Sheet	
	•		
12. PHOTO:		13. MAP:	

12. PHOTO:

14. THREATS TO BUILDING:	a. none known [X] b. zoning [] c. roads [] d. developers [] e. deterioration [] f. other:		
15. RELATED OUTBUILINGS AN	D PROPERTY: a. barn [] b. carriage house [] c. garage [X] d. privy [] e. shed [] f. greenhouse [] g. shop [] h. gardens [] i. landscape features. j. other:		
16. SURROUNDINGS OF THE BU	JILDING (check more than one if necessary): a. open land [] b. woodland [] c. scattered buildings [] d. densely built-up [] e. commercial [] f. industrial [] g. residential [X] h. other:		
17. INTERRELATIONSHIP OF BU	JILDING AND SURROUNDINGS:		
See Continuation Sheet			
18. OTHER NOTABLE FEATURE (Including interior features if			
See Continuation Sheet			
SIGNIFICANCE 19. DATE OF INITIAL CONSTRU	CTION: ca. 1905		
ARCHITECT:			
BUILDER:			
20. HISTORICAL AND ARCHITE	CTURAL IMPORTANCE:		
See Continuation Sheet			
21. SOURCES:			
See Continuation Sheet			
22. THEME:			

CONTINUATION SHEET, Page 1 238 Chestnut Street Corning, New York

11C. MAJOR ALTERATIONS AND DATES:

No major alterations are known to have been made to the exterior of the house since it was built ca 1905, according to the Sanborn maps.

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

The house is located in the north section of lot 9, block 74 to the east side of Chestnut Street. The residence is one of a row of late nineteenth- and early twentieth-century homes. The setback, scale, and style of this house are inconsistent with that of its neighbors to both sides which are a double-house to the north and a "Hipped Bungalow" to the south. The north-to-south spacing is also inconsistent.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE:

An example of the vernacular Queen Anne Style, this residence can also be defined as a "gabled-ell cottage" according to Herbert Gottfried & Jan Jennings in their book <u>American Vernacular Design</u>. Gabled-ell cottages are notable for their intersecting gables, sometimes with one clipped gable which receives applications of shingles or stickwork ornament.

The central gabled section of this residence projects out toward Chestnut Street. The principal facade is oriented to the west. The porch in the ell is located on the north side of the house. It has a closed railing and turned posts. The fenestration is symmetrical in all facades excepting on the east. The windows are primarily one-over-one double-hung sash. A square window is centered in the gable end.

The house is sided in wood clapboard shingles. The roof is done in asphalt shingles. The foundation wall is prominent and is parged in cement.

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

This house is located on lot 9, block 74 as shown on the 1855 Brewer and Canfield map of Corning. According to Auwaerter, the development of this section of the Southside neighborhood of Corning, occurred slowly, and "as late as 1911, there was much open land along Fifth Street and above." There were many Irish people living on this area of the Southside neighborhood to the point of being called "Irish Hill". Albert Sullivan, who was a glass cutter owned a house on this parcel ca. 1893. In 1922, William Holmes bought the house in which three generations of Holmes have lived. William Sidney Holmes Jr. passed the house on his son Marion, as his last will on December, 1980. The Holmes also owned the house next doors on 240 Chestnut Street in 1922.

CONTINUATION SHEET, Page 2 238 Chestnut Street Corning, New York

21. SOURCES:

Auwaerter, John. Reconnaissance Level Survey. Southside Neighborhood Proposed Historic District. Corning, New York, 1991.

Gottfried, Herbert et Jennings Jan. American Vernacular Design. 1870—1940. Iowa State University Press. 1988.

New York, Corning and Painted Post Directory 1893, 1905, 1915-1916, 1936, 1939, 1944, 1947, 1950, 1952, 1953, 1955,1956, 1958, 1959, 1962, 1964, 1965, 1967, 1970, 1978, 1986.

Sanborn Map Company. Fire insurance Maps of Corning, New York (1898, 1903, 1908, 1913, 1921, 1930 and 1948).

Steuben County Deed Records, Steuben County's Clerk's Office, Bath, NY. Liber 1012, page 851.

Steuben County, tax rolls, Steuben County's Tax rolls Office, Bath, NY, 1920, 1922.

ADDITIONAL PHOTOGRAPHS:

Northeast Facade







