BUILDING-STRUCTURE INVENTORY FORM				FOR OFFICE USE ONLY		
DIV	ISION FOR HISTOR	IC PRESE	TRVATION	UNIOUE SITE	UNIOUE SITE NO	
ME	W YORK STATE PAR	SKS AND	PECDEATION	QUAD		
ALE	BANY, NEW YORK (	518) 474-(	0479	DEVIED		
				NEG. NO		
JOY	JR NAME: Gene Gre	ger		DATE: Fall 10	DATE: Fall 1993	
JUY	JR ADDRESS: 106 W	V. Sibley F	Hall, Ithaca, NY			
UKC	GANIZATION (if any)	: Preserva	ation Planning Wo	orkshop, Cornell Univ	(007) 233-4331 versity	
****	******	و و . و . و . و و ماه ماه ماه ماه ماه ماه		1,	Cisity	
	*********	******	**********	************	*******	
1.	BUILDING NAME	(2).				
2.	COUNTY: Steu	hon	TOMBLIC			
3.	STREET LOCATION	)Ni- 264 W	TOWN/C	ITY: Corning	VILLAGE:	
4.	OWNERSHIP	a nubli	α [] L · · ·	EX 23		
5.	PRESENT OWNER: Emmanuel C & Furba I Omin 1 APPROX					
6.	USE: Original: sin	SE: Original: single-family residence Present: single-family residence CCESSIBILITY TO PUBLIC: Exterior visible for				
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road Yes[X]					y residence	
		Interior	accessible. Ves [	No [X] Explain:	es[X] No []	
			accessione. Tes [	j No [A] Explain:	Private Residence	
DESC	CRIPTION					
8.	BUILDING MATE		a. clapboard[X] b.	stone[] c. brick[] d. b	20 and 0 1 17	
		6	e. cobblestone[] f.	shingles[] g. stucco[]	other:	
9.	CTDIIOTID AT GT					
<b>J.</b>	STRUCTURAL SY					
		ι	wood frame wit	h light members[X]		
		C	: masonry load be	caring walls[]		
			l. metal			
		e	. other (explain)			
10.	CONDITION:	a. excellent[] b. good[X] c. fair[] d. deteriorated[]				
	CONDITION.	a. excelle	ent[] b. good[X] c	. fair[] d. deteriorated		
11.	INTEGRITY:	<ul><li>a. original site[X] b. moved[] if so, when?</li><li>c. list major alterations and dates (if known):</li></ul>				
			jo- anoranons and	i dates (II known):		
12.	РНОТО:			13. MAP:		
				AD. IVIZ II .		

14. THREATS TO BUILDING: a. none known[X] b. zoning[] c. roads[] d. developers[] e. deterioration[] f. other:

15. RELATED OUTBUILDINGS AND PROPERTY:

a. barn[] b. carriage house[] c. garage[]d. privy[] e. shed[] f. greenhouse[]

g. shop[] h. gardens[] i. landscape features:

i. other:

16. SURROUNDINGS OF THE BUILDING: (Check more than one if necessary)

a. open land[] b. woodland[]

c. scattered buildings[]

d. densely built-up[] e. commercial[]

f. industrial[] g. residential[X]

h. other:

17. INTERRELATIONSHIP OF BUILDINGS AND SURROUNDINGS:

See Continuation Sheet

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE: (Including interior features if known):

See Continuation Sheet

### **SIGNIFICANCE**

19. DATE OF INITIAL CONSTRUCTION: ca. 1870

ARCHITECT:

BUILDER:

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

See Continuation Sheet

21. SOURCES:

See Continuation Sheet

22. THEME:

CONTINUATION SHEET, Page 1 264 Walnut Street Corning, NY

### 11c. MAJOR ALTERATIONS AND DATES:

Several modifications to this structure were made after 1948; the exact dates are unknown. A single-story L-shaped wing was removed from the rear (east) of the house. A single-story porch located in the northwest corner of the house was removed from the north facade. A two-story wing was added to the southeast side of the building forming an L-shape. A new entranceway with a shed roof was put in the corner formed by adding the new wing.

# 17. INTERRELATIONSHIP OF BUILDINGS AND SURROUNDINGS:

Situated on the east side of Walnut Street, this residence is one of a row of nineteenth- and early twentieth-century homes. The styles, spacing, setback, and sizes of the houses are inconsistent.

### 18. OTHER NOTABLE FEATURES OF BUILDING AND SITE:

This two-story house has a gable-front-and-wing shape. The gable-front wing forms the north side of the house and features a single-story bay window. The second wing intersects the first at the northeast corner of the house and continues south. The south half of this side-gable wing is larger than the north half and projects out of the east facade. A small single-story shed roof covers the entranceway located in the corner formed by the two wings. An end-wall concrete block chimney is situated on the south facade.

## 20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

This house is constructed on the northern half of Lots #9 and #10 of Block 70, as laid out in the 1855 Brewer and Canfield map of Corning. This house may have been built by Andrew Schwarzenback who later occupied a now destroyed house on the southern half of Lots #9 and #10. In 1893 the house was occupied J.F.C. Lindner; his occupation is unknown.

#### 21. SOURCES:

McAlester, Virginia & Lee. A Field Guide to American Houses. New York: Alfred A. Knopf, 1991.

Map of Corning. Buffalo: H. Brewer and C.A. Canfield, 1855.

Map of Corning. Corning: Harry C. Heermans, City Engineer, 1893.

Sanborn Map Company. Fire Insurance Maps of Corning, New York, (1913, 1921, 1930, and 1948).

Corning City Directories, Boyd's 1872-73, 1874-75; Hanford 1893-1920.

Corning Tax Records, Steuben County Record and Archives, Steuben County Infirmary, Bath, NY.

Steuben County Deed Records, Steuben County Clerk's Office, Bath, NY



264 Walnut